

Fluke 8840A-9005 488 GPIB PCB Revised: Thursday, May 16, 2024

Revision: 1.5

Item	Seq	Qty	Reference	Part	Part #	Vendor	Mfgr	FlukePart #
1	1i	2	CR901,CR902	1N748	1N748ATR	Mouser	Central	1N748
2	1j	5	CR903,CR904,CR905,CR906,CR910	1N4448	1N914	HWC		1N4448
3	1k	2	CR908,CR909	1N4002A	1N4002A	HWC		1N4002A
4	2a	1	C901	1.0uF T	TAP105M035CCS	Mouser	AVX	199D105X0035AG2
5	2b	4	C902,C903,C907,C908	0.01uF	K103Z15Y5VE5TH5	Mouser	Vishay	562CZ5USE50EE103M
6	2c	1	C909	430pF	C323C431KAG5TA	Mouser	KEMET	SR595A431JAA
7	10a	1	C910	4700uF	UVR1C472MHD	Mouser	Nichicon	KME16VN472K23X27LLV
8	2d	9	C911,C918,C919,C920,C923,C925,C926,C927,C928	0.22uF	FG24X7R1H224KNT00	Mouser	TDK	SR595E224ZAA
9	2e	1	C914	0.001uF	K102K10X7RF5UH5	Mouser	Vishay	SR595C102MAA
10	2f	1	C915	47uF T	TAP476K010CCS	Mouser	AVX	199D476X0010DG2
11	2g	2	C921,C922	18pF	FG28COG1H180JNT00	Mouser	TDK	SR595A150MAA
12		3	E902,E903,E904	JUMPER	E902 def			
13	3a	1	E905	JMP2				
14	8a	1	J901	488-GPIB	554923-2	eBay	AMP	554923-2
15	9a	1	J902	CON10	D3793-6302-AR	Mouser	3M	3446-6322
16	8c	1	J903	SAMPLE COMP	5227161-1	Mouser	TEC	911487
17	8c	1	J904	EXT TRIG	5227161-1	Mouser	TEC	911487
18		2	MH1,MH2	M HOLE1				
19	3b	1	RV901	EMIFILTER	DSS1NB32A223Q91A	Mouser	Murata	DSS71091D223S12-22M
20	1a	2	R911,R912	33K		HWC		
21	1b	2	R913,R914	1.5K		HWC		
22	1c	3	R915,R916,R919	470		HWC		
23	1d	3	R917,R918,R938	100		HWC		
24	1e	1	R920	3.3K		HWC		
25	1f	1	R943	68K		HWC		
26	1g	1	R944	51K		HWC		
27	1h	3	R945,R946,R947	10K		HWC		
28	19a	1	S901	ADDRESS	335802-1	eBay	AMP	1-435802-5
29	6a	2	TP901,TP906	DATA	62395-1	Mouser	TEC	62395-1
30	6a	1	TP902	5	62395-1	Mouser	TEC	62395-1
31	6a	1	TP903	COM	62395-1	Mouser	TEC	62395-1
32	6a	1	TP905	TEST POINT	62395-1	Mouser	TEC	62395-1
33	17a	1	U901	Z86E21	ST Z86E21AF1	eBay	ST	879270
34	15a	1	U905	74LS368X	74LS368AN	TI	TI	SN74LS368AN
35	15a	1	U908	LM339A	LM339N	HWC		LM339N
36	15a	1	U909	74LS14	SN74LS14N		TI	SN74LS14N
37	15a	1	U910	74LS32	SN74LS32N		TI	SN74LS32N
38	17b	1	U911	UPD7210C	NAT7210B	eBay		UDP7210C/D
39	16a	1	U912	SN75LS160	SN75161BN	TI	TI	SN75161BN
40	16b	1	U913	SN75LS161	SN75160BN	TI	TI	SN75160BN
41	7c	1	VR901	LM7805/TO	LM7805	HWC	NATL	MC7805T
42	11a	1	Y901	8Mhz	ECS-080-18-1X	Mouser	ECS	HC-18U-8.00
43	5a	1	Z903	MDP14-01-332J	MPD14-01-332J	eBay	Dale	MPD14-01-332J
44	9a	1	J902A	Pol-Pin		Mouser		
45	4a	1	XU901,XU911	socket blade 40p		Mouser		
46	4a	6	XU905,XU908,XU909,XU910,XU912,XU913	sockets		HWC		
47	7a	1	XVR901	heat sink	6030B-TTG	Mouser		
48	18a	2	XH6,7	NY_Latch rivet	NY4G-44-20	Southco	Southco	HN4G-44-1
49	18b	2	XH8,9	NY_Latch pin	NY4P-44-4-50	Southco	Southco	HN4P-44-4-1
50	7b	1	XH4	nut 6-32		HWC		
51	7b	1	XH5	screw pan 6-32x5/16		HWC		
52	8b	2	XH10	#6 HPIB jack screw		AVNET		
53		1	XH11	9005_PCB_AM3A		HWC		